


Montageanleitung für den KESSEL-Klebeflansch und KESSEL-Pressdichtungsflansch

(Bestell-Nr.: 48401, 48410, 48402)

passend für KESSEL-Grundkörper Practicus, Ecoguss und Ultraflach (45740, 45770, 45701)



1. Den O-Ring in die obere Nut des Grundkörpers einsetzen und einfetten.




2. Bei der Montage des Klebeflansches mit dem Grundkörper DN 100, Ablauf seitlich ist zu beachten, dass sich die Schraubpunkte nicht direkt unter dem Ablauf befinden, da sonst Teilekollision auftritt.



3. Den Grundkörper erst auf einer Seite in den Flansch stecken und in Pfeilrichtung herunter drücken.

4. Nach der Montage den korrekten Sitz des O-Rings und der Verclipsung überprüfen.



Hinweis:

Pressdichtungsflansch und Grundkörper sind max. 70 kg belastbar.

Fitting instructions for the KESSEL adhesive flange and KESSEL pressure sealing flange

(Order-Nr.: 48401, 48410, 48402)

for the KESSEL drain bodies Practicus and Ecoguss
Ultra flat (45740, 45770, 45701)




1. Insert the O-ring in the upper groove of the drain body and grease it

2. When fitting the adhesive flange onto the drain body DN 100, side outlet, care must be taken that the screwing points are not directly under the drain, as otherwise part collision will occur



3. Insert the drain body into the flange on one side first, and press down in the direction of the arrow

4. After fitting, check the O-ring and the clips for a correct fit



Note:

Max. load on pressure sealing flange and drain body is 70 kg.