

Tucherbräu at the opera house

Nuremberg's traditional pub in new splendour.



Source: Andrea Nash / Stadt Nürnberg



On-site welding of the grease separator with subsequent quality and leak test. (Source: SHK TV)

The "Tucherbräu am Opernhaus" in Nuremberg, which has been vacant since 2012, will be completely renovated by 2022. The original listed building was destroyed down to its foundation walls during the Second World War. It was rebuilt between 1946 and 1949 and is currently being modernised during the refurbishment. Since all technical requirements had to be adapted to the given premises on site, it was decided that the grease separator would be welded and assembled in its final location.

Selection Criteria

- Highest hygiene standard thanks to Ferrofix stainless steel drains
- The disposal intervals can be lengthened by permanent monitoring using the SonicControl layer thickness measuring device
- Extensive services from the design to operation of the installation
- Odourless drainage and cleaning process possible in a closed system

Products Used In Reference Object

- Ferrofix System 125 project drain
- Ecoguss drain body
- Aqualift F XL, 300 l lifting station
- EasyClean free Auto Mix & Pump
- Ferrofix box channel